

Anexo C. Series de ventiladores modelos HT70 y HT70 Plus impactados por FCA 1479 (Alerta sanitaria 230/25) en Chile

A continuación, se detallan las series de ventiladores HT70 y HT70 Plus impactados por FCA 1479 (Alerta sanitaria 230/25).

Series impactadas		
N11HT700611687	N17HT721121364	HT7P190426
N11HT701212812	N17HT720120029	HT7P190428
N14HT701117097	N17HT720120030	1850DA029
N14HT701117101	N18HT720321875	2046DA028
N16HT720219091	N16HT720118976	N15HT721018714
N16HT720219078	N16HT720118981	N15HT721018716
N13HT720612038	N16HT720118992	N15HT721118833
N16HT720219077	N16HT720119005	N16HT720118978
N16HT720219090	HT7P180438	N16HT720118980
N15HT720616649	N14HT720413505	N16HT720118982
N16HT720219088	N16HT720118977	N16HT720118983
N16HT720219075	N11HT700611690	N16HT720118993
N16HT720118989	N14HT720413478	N16HT720118994
N16HT720118979	N14HT720413480	N16HT720118998
N16HT720219087	N16HT720118984	N16HT720119001
N13HT721212964	N16HT720119000	N16HT720119004
N12HT720610374	N16HT720118985	N16HT720119007
N16HT720119002	N16HT720118987	N16HT720219073
N16HT720219068	N16HT720119006	N15HT720518122
N15HT720518129	N16HT720118990	
N15HT721118834	N16HT720118991	
N17HT720120038	HT7P180460	
N18HT720321858	N15HT721118836	
N17HT721121349	N15HT721018715	
N17HT721121348	HT7P200212	

